

HISTORIC AMERICAN ENGINEERING RECORD

HAER
UTAH
27-HURIV,
1-

Virgin River Bridge (Harrisburg River)
Spanning Virgin River on State Route 9
Hurricane vicinity
Washington County
Utah

HAER No. UT-59

NOTE: Photographs were taken by John Jelte, photographer, August 1990

- UT-59-1 VIEW OF EAST APPROACH TO BRIDGE
- UT-59-2 VIEW OF WEST APPROACH TO BRIDGE
- UT-59-3 VIEW OF NORTH SIDE OF BRIDGE
- UT-59-4 DETAIL VIEW OF OPEN SPANDREL ARCH, PILLARS, AND RAILING ON
NORTH SIDE OF BRIDGE, LOOKING WEST
- UT-59-5 VIEW OF SOUTH SIDE OF BRIDGE, SHOWING ENCLOSED SPANDREL
ARCH AND BRIDGE NAMEPLATE, LOOKING EAST
- UT-59-6 VIEW OF SOUTH SIDE OF BRIDGE, SHOWING OPEN SPANDREL,
LOOKING EAST FROM SLIGHTLY BELOW BRIDGE
- UT-59-7 VIEW OF OPEN SPANDREL ARCH PORTION AND REPLACEMENT
BRIDGE ON SOUTH SIDE OF BRIDGE
- UT-59-8 VIEW LOOKING WEST BENEATH SECOND ENCLOSED SPANDREL ARCH
- UT-59-9 DETAIL VIEW OF ROLLING EXPANSION JOINT, NORTHEAST BASE OF
SECOND CLOSED SPANDREL ARCH AT JUNCTION OF OPEN SPANDREL
ARCH, LOOKING EAST